

underautomated. (Final rule; extension of compliance date, 59 FR 39425, August 3, 1994). The compliance date remains January 1, 1995, for all other credit unions.

Legislative Activity

Since the last extension, several bills have been introduced into the 104th Congress of the United States to either repeal, or restrict the scope of TISA. "A bill to repeal the Truth in Savings Act," H.R. 337, introduced in the House of Representatives on January 4, 1995, would repeal TISA. The "Financial Institutions Regulatory Relief Act of 1995," H.R. 1858, introduced in the House of Representatives on June 15, 1995, would amend TISA by repealing many of its disclosure requirements and civil liability provisions. Section 270(3)(B) of H.R. 1858 excludes "nonautomated credit unions which were not required to comply with the requirements of [TISA] as of the date of the enactment of [H.R. 1858] pursuant to the determination of the NCUA Board." The "Economic Growth and Regulatory Paperwork Reduction Act of 1995," S. 650, introduced in the Senate on March 30, 1995, would repeal TISA and replace it with the Payment of Interest Act (PIA). PIA basically eliminates TISA's disclosure requirements, but retains the requirement that interest and dividends on accounts be calculated on the full amount of principal in the account for each day and at the rate(s) disclosed by the depository institution.

Importance of Small Credit Unions

The NCUA Board is very concerned with the continued viability of small credit unions. Ten years ago, credit unions under \$2 million in size made up about two-thirds (10,564) of all federally insured credit unions. Today, such credit unions number only 3,666, about one-third of federally insured credit unions. In addition, the assets of today's 3,666 smallest credit unions are approximately one percent of total assets in all credit unions, while credit unions of \$2 million or less accounted for 7.7 percent of total assets ten years ago. The average credit union today has \$25.4 million in assets, compared to \$5 million ten years ago.

However, many of these small credit unions are already automated or have in-house data processing capabilities, and have not been covered by previous exemptions. Only a small number of credit unions are affected by this amendment and extension. NCUA previously determined that there were 1,248 credit unions under \$2 million in assets that have no or insufficient or

inadequate computers or in-house data processing capability.

Given Congressional legislative activity, and requests for a postponement in the Official Staff Commentary from national trade associations, the Board has decided, in the name of regulatory relief and in the spirit of the National Performance Review and Presidential Regulatory Reform Initiative, to delay the compliance date of part 707 until January 1, 1997 for affected credit unions. A compliance date extension of this length will enable the NCUA to observe and implement any possible legislative initiatives by the 104th Congress, while also providing continued regulatory relief to presently exempted credit unions. In the meantime, the Board continues to support several small credit union initiatives to continue the development of small credit unions. Recently, the Board authorized an NCUA Conference on "Serving the Underserved" scheduled for August of 1996. The purpose of this conference is to provide opportunities for education, networking between different asset size credit unions, and to find solutions to availability of service issues faced by the agency and credit unions. In April of 1994, the NCUA Board adopted a program to place retired NCUA computers with nonautomated credit unions with \$2 million or less in assets. To date, 435 small credit unions have participated in this program and received retired NCUA examiner laptop computers. The Board is also working on several other initiatives to enhance small credit union development.

The compliance date has remained January 1, 1995, for all other credit unions (automated credit unions under \$2 million in assets and all credit unions having over \$2 million or more in assets).

Definition of Nonautomated

NCUA generally uses the December 31, 1994, NCUA Form 5300 report to determine the requisite nonautomation status and asset size for those credit unions filing Form 5300 reports that are eligible for the extensions in required compliance.

Credit unions which do not file Form 5300 reports will be permitted to prove nonautomation status and asset size by other means. By the term "nonautomation status" NCUA means those credit unions without adequate and sufficient computer or data processing capacity and capability to operate and maintain a share and loan software program able to cover all member accounts at the credit union.

NCUA will consider verified self-certifications, certifications by appropriate state supervisory authorities, and other equivalent forms of proof as sufficient for eligibility for the extension by non-federally insured credit unions. With the assistance of the affected credit unions, trade groups, and the NCUA regional and central office staffs, NCUA has identified credit unions in need of Truth in Savings compliance assistance, and is providing various educational and other assistance to the affected small, nonautomated credit unions.

Credit unions currently exempt, that surpass the \$2 million asset threshold during the 1995 calendar year, should plan to comply with TISA on January 1, one year subsequent to the year end reporting cycle in which they report assets over \$2 million.

Administrative Procedure Act

The amendment and extension made to this part are not subject to the notice and comment provisions of the Administrative Procedure Act (APA), 5 U.S.C. 551 *et seq.* The extension relates to a few credit unions that need more time and assistance in complying with part 707. No major changes are contemplated, or made, by this amendment and extension. Therefore, the NCUA Board has determined that, in this case, the APA notice and comment procedures for this amendment and extension are impracticable, unnecessary, and contrary to the public interest. 5 U.S.C. 553(b)(3)(B).

By the National Credit Union Administration Board on November 6, 1995.
Becky Baker,

Secretary of the Board.

[FR Doc. 95-28014 Filed 11-13-95; 8:45 am]

BILLING CODE 7535-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 95-NM-206-AD; Amendment 39-9426; AD 95-23-06]

Airworthiness Directives; British Aerospace Model BAe 146-100A, -200A, and -300A Airplanes and Model Avro 146-RJ70A, -RJ85A, and RJ-100A Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; request for comments.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that is

applicable to certain British Aerospace Model BAe 146-100A, -200A, and -300A airplanes and Model Avro 146-RJ70A, -RJ85A, and RJ-100A airplanes. This action requires inspections to detect cracking and evidence of exhaust leaks in the forward face of the central panel of the forward firewall of the auxiliary power unit (APU) bay, and replacement of the central panel with a new panel, if necessary. This amendment is prompted by a report indicating that cracking due to leakage of hot exhaust gases was found in the forward face of the forward firewall of the APU bay. The actions specified in this AD are intended to prevent such gas leakage and subsequent cracking, which could damage the wiring to the APU fire bottle; this condition could result in failure of the APU fire bottle to discharge in the event of an APU fire.

DATES: Effective November 29, 1995.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of November 29, 1995.

Comments for inclusion in the Rules Docket must be received on or before January 16, 1996.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-103, Attention: Rules Docket No. 95-NM-206-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. The service information referenced in this AD may be obtained from British Aerospace Holding, Inc., Avro International Aerospace Division, P.O. Box 16039, Dulles International Airport, Washington, DC 20041-6039. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Tim Backman, Aerospace Engineer, Standardization Branch, ANM-113, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (206) 227-2797; fax (206) 227-1149.

SUPPLEMENTARY INFORMATION: The Civil Aviation Authority (CAA), which is the airworthiness authority for the United Kingdom, recently notified the FAA that an unsafe condition may exist on certain British Aerospace Model BAe 146-100A, -200A, and -300A airplanes and Model Avro 146-RJ70A, -RJ85A, and RJ-100A airplanes. The CAA advises that it received a report indicating that cracking was found in the aluminum

face plate on the forward side of the central panel of the forward firewall of the auxiliary power unit (APU) bay on a British Aerospace Model BAe 146 series airplane. Hot exhaust gases escaped through the sealing system used around the duct at the central panel of the forward firewall of the APU bay. Exposure to these hot gases resulted in cracking of the aluminum alloy portion of the central panel. Leakage of additional hot gases through the seal and resultant cracking could damage the wiring to the APU fire bottle. This condition, if not corrected, could result in failure of the APU fire bottle to discharge in the event of an APU fire.

British Aerospace has issued Service Bulletin S.B.26-35, Revision 1, dated August 30, 1995, which describes procedures for repetitive close detailed visual inspections to detect cracking and evidence of exhaust leaks in the forward face of the central panel of the forward firewall of the APU bay. For airplanes on which both cracking and evidence of gas leakage are found, the service bulletin specifies that operation of the APU must be prohibited either when the aircraft is on the ground or in flight until the central panel has been replaced with a new panel. The CAA classified this service bulletin as mandatory in order to assure the continued airworthiness of these airplanes in the United Kingdom.

British Aerospace also has issued Service Bulletin SB.26-35-36179A, dated August 4, 1995, which describes procedures for replacement of the central panel (constructed of aluminum alloy) of the forward firewall of the APU bay with a new panel constructed of titanium TA2 (Modification HCM36179A). The modification also involves replacing the associated stiffeners. The titanium central panel will provide better resistance to cracking at high temperatures. Accomplishment of this modification eliminates the need for repetitive inspections of the forward face of the central panel of the forward firewall of the APU bay.

For airplanes on which the previously described modification has not been accomplished, British Aerospace also has issued Service Bulletin SB.26-36-36179B, dated June 22, 1995, which describes procedures for installation of a protective aluminum alloy shield on the vertical stiffener (left-hand) next to the exhaust aperture of the forward firewall of the APU bay (Modification HCM36179B). Accomplishment of the installation provides protection of the wiring installation of the APU fire bottle. The service bulletin specifies that accomplishment of this installation

increases the interval for repetitive inspections of the forward face of the central panel of the forward firewall of the APU bay to coincide with regularly scheduled maintenance of the affected airplanes.

These airplane models are manufactured in the United Kingdom and are type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the CAA has kept the FAA informed of the situation described above. The FAA has examined the findings of the CAA, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design registered in the United States, this AD is being issued to prevent leakage of hot exhaust gases and subsequent cracking of the forward face of the forward firewall of the APU bay, which could damage the wiring to the APU fire bottle and result in failure of the APU fire bottle to discharge in the event of an APU fire. This AD requires repetitive close detailed visual inspections to detect cracking and evidence of exhaust leaks in the forward face of the central panel of the forward firewall of the APU bay, and replacement of the central panel with a new panel, if necessary. Such replacement, if accomplished, constitutes terminating action for the requirements of this AD. For airplanes on which cracking and evidence of gas leakage are found, this AD also prohibits operation of the APU (either when the aircraft is on the ground or in flight) until the central panel has been replaced with a new panel. This AD also provides for installation of a protective aluminum alloy shield on the vertical stiffener (left-hand) next to the exhaust aperture of the forward firewall of the APU bay, which, if accomplished, increases the interval for repetitive inspections of the forward face of the central panel of the forward firewall of the APU bay. The actions are required to be accomplished in accordance with the service bulletins described previously.

Operators should note that, for airplanes on which cracks are found, but no evidence of gas leakage is found, British Aerospace Service Bulletin S.B.26-35 recommends that daily inspections be accomplished and that

corrective action be accomplished at the "next convenient downtime." This AD, however, requires daily inspections and accomplishment of the corrective action (replacement of the central panel) within 14 days after crack detection. The FAA finds that a 14-day compliance time will address the unsafe condition in a timely manner and will decrease reliance on daily inspections, which require approximately one work hour to perform.

Since a situation exists that requires the immediate adoption of this regulation, it is found that notice and opportunity for prior public comment hereon are impracticable, and that good cause exists for making this amendment effective in less than 30 days.

Comments Invited

Although this action is in the form of a final rule that involves requirements affecting flight safety and, thus, was not preceded by notice and an opportunity for public comment, comments are invited on this rule. Interested persons are invited to comment on this rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified under the caption **ADDRESSES**. All communications received on or before the closing date for comments will be considered, and this rule may be amended in light of the comments received. Factual information that supports the commenter's ideas and suggestions is extremely helpful in evaluating the effectiveness of the AD action and determining whether additional rulemaking action would be needed.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the rule that might suggest a need to modify the rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report that summarizes each FAA-public contact concerned with the substance of this AD will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this rule must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 95-NM-206-AD." The postcard will be date stamped and returned to the commenter.

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the

national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

The FAA has determined that this regulation is an emergency regulation that must be issued immediately to correct an unsafe condition in aircraft, and that it is not a "significant regulatory action" under Executive Order 12866. It has been determined further that this action involves an emergency regulation under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979). If it is determined that this emergency regulation otherwise would be significant under DOT Regulatory Policies and Procedures, a final regulatory evaluation will be prepared and placed in the Rules Docket. A copy of it, if filed, may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 USC 106(g), 40101, 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

95-23-06 British Aerospace Regional Aircraft Limited, Avro International Aerospace Division (Formerly British Aerospace, plc; British Aerospace Commercial Aircraft Limited): Amendment 39-9426. Docket 95-NM-206-AD.

Applicability: Model BAe 146-100A, -200A, and -300A airplanes, and Model Avro 146-RJ70A, -RJ85A, and RJ-100A airplanes; on which British Aerospace Modification HCM36019A is installed; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this

AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must use the authority provided in paragraph (d) of this AD to request approval from the FAA. This approval may address either no action, if the current configuration eliminates the unsafe condition; or different actions necessary to address the unsafe condition described in this AD. Such a request should include an assessment of the effect of the changed configuration on the unsafe condition addressed by this AD. In no case does the presence of any modification, alteration, or repair remove any airplane from the applicability of this AD.

Compliance: Required as indicated, unless accomplished previously.

To prevent leakage of hot exhaust gases and subsequent cracking of the forward face of the forward firewall of the auxiliary power unit (APU) bay, which could damage the wiring to the APU fire bottle and result in failure of the APU fire bottle to discharge in the event of an APU fire, accomplish the following:

(a) Within 7 days after the effective date of this AD: Perform a close detailed visual inspection to detect cracking and evidence of exhaust leaks in the forward face of the central panel of the forward firewall of the APU bay, in accordance with British Aerospace Service Bulletin S.B.26-35, Revision 1, dated August 30, 1995.

Note 2: Inspections accomplished prior to the effective date of this AD in accordance with British Aerospace Service Bulletin S.B.26-35, dated May 17, 1995, are considered acceptable for compliance with the applicable action specified in this amendment.

(1) If no crack or evidence of gas leakage is found, repeat the inspection required by paragraph (a) of this AD thereafter at intervals not to exceed 200 landings, except as provided by paragraph (b) of this AD.

(2) If any crack is found, but no evidence of gas leakage is detected, repeat the inspection required by paragraph (a) of this AD thereafter at daily intervals. Within 14 days after detecting any crack, accomplish the replacement specified in paragraph (c) of this AD.

(3) If any crack is found and evidence of gas leakage is detected, prior to further flight, accomplish the replacement specified in paragraph (c) of this AD. Operation of the APU is prohibited (either when the aircraft is on the ground or in flight) until the replacement is accomplished.

(b) Installation of a protective aluminum alloy shield on the vertical stiffener (left-hand) next to the exhaust aperture of the forward firewall of the APU bay (Modification HCM36179B), in accordance with British Aerospace Service Bulletin SB.26-36-36179B, dated June 22, 1995, increases the interval for repetitive inspections required by paragraph (a)(1) of this AD from 200 landings to 400 landings.

(c) Replacement of the central panel of the forward firewall of the APU bay with a new panel (Modification HCM36179A), in

accordance with British Aerospace Service Bulletin SB.26-35-36179A, dated August 4, 1995, constitutes terminating action for the requirements of this AD.

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Standardization Branch, ANM-113, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Standardization Branch, ANM-113.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Standardization Branch, ANM-113.

(e) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(f) The actions shall be done in accordance with British Aerospace Service Bulletin S.B.26-35, Revision 1, dated August 30, 1995; British Aerospace Service Bulletin SB.26-35-36179A, dated August 4, 1995; and British Aerospace Service Bulletin SB.26-36-36179B, dated June 22, 1995. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from British Aerospace Holding, Inc., Avro International Aerospace Division, P.O. Box 16039, Dulles International Airport, Washington DC 20041-6039. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(g) This amendment becomes effective on November 29, 1995.

Issued in Renton, Washington, on November 6, 1995.

Darrell M. Pederson,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 95-27913 Filed 11-13-95; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF LABOR

Office of Labor-Management Standards

29 CFR Part 452

RIN 1294-AA09

Eligibility Requirements for Candidacy for Union Office

AGENCY: Office of Labor-Management Standards, Labor.

ACTION: Final rule.

SUMMARY: The Office of Labor-Management Standards is amending its

interpretative regulations on labor organization officer elections. The amendment will add a reference to a ruling by the Court of Appeals for the District of Columbia Circuit regarding the reasonableness of meeting attendance requirements set by labor organizations for eligibility for union office. This amendment will inform the public of a court decision that guides the Office in its enforcement actions.

EFFECTIVE DATE: December 14, 1995.

FOR FURTHER INFORMATION CONTACT: Kay H. Oshel, Chief, Division of Interpretations and Standards, Office of Labor-Management Standards, Office of the American Workplace, U.S. Department of Labor, 200 Constitution Avenue, NW., Room N-5605, Washington, DC 20210, (202) 219-7373. This is not a toll-free number.

SUPPLEMENTARY INFORMATION: Title IV of the Labor-Management Reporting and Disclosure Act of 1959, as amended (LMRDA) sets forth standards and requirements for the election of labor organization officers. Section 401(e) of title IV, 29 U.S.C. 481(e), provides in part that every member in good standing has the right to be a candidate subject "to reasonable qualifications uniformly imposed."

In connection with the Department's enforcement responsibilities under LMRDA title IV, interpretative regulations have been promulgated, 29 CFR Part 452, in order to provide the public with information as to the Secretary's "construction of the law which will guide him in performing his [enforcement] duties." 29 CFR § 452.1. Several provisions in the interpretative regulations discuss union-imposed qualifications on candidacy eligibility. One of these provisions, 29 CFR § 452.38, deals specifically with meeting attendance requirements and lists several factors to consider in determining whether, under "all the circumstances," a particular meeting attendance requirement is reasonable.

On June 15, 1994, OLMS published an advance notice of proposed rulemaking (ANPRM) requesting comments from the public on the possible need to modify the interpretative regulations on meeting attendance requirements in order to incorporate a ruling of the United States Court of Appeals for the District of Columbia Circuit in *Doyle v. Brock*, 821 F.2d 778 (D.C. Cir. 1987). In *Doyle*, the Secretary had decided not to bring civil action on a member's complaint about his union's meeting attendance requirement, even though the requirement disqualified 97% of the members. The Secretary's position, after reviewing the factors set forth in 29 CFR

§ 452.38, was that since the requirement was not on its face unreasonable (i.e., it did not require a member to decide to become a candidate an excessively long period before the election) and it was not difficult to meet (i.e., the meetings were held at convenient times and locations and the union provided liberal excuse provisions), the large impact of the requirement was not by itself sufficient to render it unreasonable. The district court ruled against the Secretary, *Doyle v. Brock*, 641 F. Supp. 223 and 632 F. Supp. 256 (D.D.C. 1986), and the court of appeals affirmed the lower court.

After reviewing the comments submitted on the ANPRM, the Department published a notice of proposed rulemaking (NPRM) on May 17, 1995 (60 FR 26388). The NPRM proposed revising 29 CFR 452.38 by replacing the current text of footnote 25 with a brief summary of the holding in *Doyle* that a meeting attendance requirement may be unreasonable solely on the basis of its impact in rendering members ineligible.

One comment from an individual was received on the NPRM. That comment wanted to have meeting attendance requirements banned because they impede challenges to current union leadership. However, as stated in the NPRM, after reviewing the comments on the ANPRM the Department has concluded that there is not a sufficient legal basis at this time to hold that meeting attendance requirements are per se unreasonable under the LMRDA. Therefore, the Department is adopting the proposal as set forth in the NPRM.

Administrative Notices

A. Executive Order 12866

The Department of Labor has determined that this proposed rule is not a significant regulatory action as defined in section 3(f) of Executive Order 12866 in that it will not (1) have an annual effect on the economy of \$100 million or more, or adversely affect in a material way the economy, a sector of the economy, productivity, competition, jobs, the environment, public health or safety, or State, local, or tribal governments or communities, (2) create a serious inconsistency or otherwise interfere with an action taken or planned by another agency, (3) materially alter the budgetary impact of entitlements, grants, user fees, or loan programs or the rights and obligations of recipients thereof, or (4) raise novel legal or policy issues arising out of legal mandates, the President's priorities, or the principles set forth in Executive Order 12866.